## Annual Walk of Town Hall - 09/09/2021

- 1. Present: Cllr Handford and the Clerk Christine Downey.
- 2. Findings as compared to condition on 09/04/2019. (There was no 2020 walk because building closed due to Covid).

	09/04/2019 findings and	09/09/2021 findings
	subsequent action	
FOYER AND LANDING:		
Foyer – general condition	Remove the carousel of TIP	OK; foyer clear.
	literature because it is	
	flammable. Done.	
Foyer – general condition	-	Paint peeling next to sliding
		door, and may be damp.
Lift entrance - ripped lino	Cannot be replaced by gripper,	OK; stuck down with safety
outside lift.	so stuck down with safety	tape.
	tape.	
Disabled ramp needs	Done by decorator Nov 2019.	Needs doing again.
resurfacing – worn and looks		
shabby.		
Lights in foyer.	-	Three lights out.
Plaster front wall on stairs and	Done by decorator Nov 2019.	OK.
landing		
Lights on landing.	Light out on landing. Replaced.	OK.
Sliding door.	-	OK; running smoothly.
Roller shutter.		OK: now rolling to the floor.
GENTS TOILETS:		
Lights	One flickering light. Replaced.	One light out.
Taps		Quote to replace leaky taps
		accepted 26/07/21. HB
		plumbing asked to proceed
		28/07/21.
Soap dispensers	Need replacing with plastic	OK.
	models. Done.	
DISBLED TOILET		
Soap dispenser	Need replacing with plastic	OK.
	models. Done.	
BALLROOM:		
Curtains	4 out of 7 curtains not closing	Resolved 26/07/21 to obtain
	properly.	quotes for black out blinds and
		for light curtains to be hung in
		addition to blackout blinds,
		with a view to improving
		acoustics.
Windows	-	Resolved 26/07/21 to obtain
		quotes for both fixing the
		blown glass and also for
		installing complete new
		replacement UPVC windows.
Fans	-	OK; now cleaned.

Ceiling tiles.	_	Four tiles over window by
Centring thes.		stage, left side (facing stage)
		stained and need replacing.
Back stage – skirting board	Short run of skirting board	Short run of skirting board
back stage — skil tillg board	missing.	missing.
Back stage - plaster	missing.	Plaster fell down at back of
back stage - plaster		stage. Cllr Adams speaking to
		Ross Chesters.
BALLROOM KITCHEN:	<u> </u>	NO33 CHESTELS.
Monoxide detector	Installed.	OK.
Drains	Persistent bad smell.	OK; no longer a bad smell
Dianis	r ersisterit bad sirieli.	present.
Door to landing	_	Needs oiling.
LADIES TOILETS:	-	iveeus onnig.
Soap dispensers	Need replacing with plastic	OK.
Soap disperisers	models. Done.	OK.
Taps	-	Quote to replace leaky taps
		accepted 26/07/21. HB
		plumbing asked to proceed
		28/07/21
WENNINGDALE ROOM.		
Ceiling tiles	One broken – one with fire	OK.
	alarm attached. Tile replaced	
	Jul 2020.	
General condition.	Needs redecorating, but need	Same as 2019.
	to consider use fist.	
WR Kitchen	-	Fan not working.
STAIRWELLS/ENTRANCES TO W		T
General condition	Damp	Damp and paint peeling at
		bottom of stairs on both sides.
General condition	-	Store room at bottom stairs
		needs thorough clear out.
Stairs down on right (facing stage)	-	Rip in carpet on half landing.
GALLEY KITCHEN:		
Servery shutter	-	Fire stopping servery shutter
·		installed - needs connecting to
		electrics. Quote accepted
		26/07/21. Howsons asked to
		proceed 28/07/21.
LOWER HALL:		
General condition	OK.	OK.
CLERKS OFFICE:		
General condition.	OK.	OK.
BELL TOWER:		
Clock	-	Clerk pursuing quote for a
		repair.
Plaster	Plaster in bell tower falling off	Not checked but will be the
	and landing on suspended	same.
	and landing on suspended	

BASEMENT:		
General condition.	-	Needs a clear out. Contains lots of light bulbs. (Christmas lights?)
General condition.	-	Water running across floor - no idea where it comes from
General condition.	-	Caretaker asked to remove litter and weeds from stairs down to basement.
UNDERPASS STORAGE AREA	A:	
General condition.	-	Needs a clear out.
General condition.	-	Light out.
OUTSIDE:	·	
Roof	Repair needed. Done Sep 2019.	OK as far as we know.
MISCA:		
Cleaners' storeroom.	Request for electric socket in store room to charge cleaner. Done.	OK.
Cleaning up equipment available to room hirers.	Very poor – request made for decent brush and shovel, washing up liquid, and dish cloths. Done.	OK.
Spinning locks.	Locks not working correctly in WR, BR, LH and GK. Considered and decided too expensive to replace the lock system.	As 2019.